

**SECRET****OUT58635****SECRET 262113Z CITE****1312**

1966 MAY 25 21 24Z 25X1

25X1

**SUBJ: EVALUATION OF MISSION C126C**

1. CAMERA B120 WAS USED IN MISSION C126C FLOWN ON 14 MAY 1966.

**PROCESSING WAS ACCOMPLISHED IN THE FIELD.**

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION WAS FAIR.

B. 9R SIDE: EDGE STATIC ON THE OUTBOARD EDGE AND ROLLER CHATTER ON THE INBOARD EDGE WERE PRESENT THROUGHOUT THE MISSION. A MANUFACTURING SPLICE LOCATED IN FRAME 875 IS ACCOMPANIED BY THE NORMAL FOG PATTERN AND HANDLING MARKS. THE NEGATIVE IS CREASED IN FRAMES 923/924. THE FILM WAS TORN AND REPAIRED IN FRAMES 1200/1201 AND PART OF 1202. FRAMES THAT SHOULD HAVE BEEN TITLED 1138 THRU 1197 WERE MISTITLED AS 1338 THRU 1397. THE FILM AFTER THIS WAS TITLED CORRECTLY. CHEMICAL STAINS WERE NOTED IN FRAMES 1368 THRU 1372. THERE WERE NUMEROUS HEAT SPLICES THROUGHOUT THE MISSION.

C. 9L SIDE: ROLLER CHATTER AND EDGE STATIC WERE NOTED ON BOTH EDGES OF THE FILM THROUGHOUT THE MISSION. A MANUFACTURING SPLICE IS LOCATED IN FRAME 84. NUMEROUS HEAT SPLICES WERE NOTED THROUGHOUT.

27 MAY 1966

DISTRIBUTION		
Cy No.	Office	Action
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
345	TID	✓
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy  
Sanitized**SECRET**GROUP 1  
Excluded from automatic  
downgrading and  
declassification 25X1

-2-

D. THE LAST TITLED FRAME IS 1563.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS IN THIS MISSION.

3. POSITIVE:

A. PI SUITABILITY IS FAIR POSSIBLY DUE TO ATMOSPHERICS.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURED APPROXIMATELY 10 PERCENT OF THE MISSION.

S E C R E T

--END OF MESSAGE--

1